

ELECTRICAL SAFETY RECALL

Scandia 'Verdant LE' Pellet Heater

Sold through Bunnings from Jan 2017 - Dec 2019



COMPLIANCE PLATE	
SCANDIA VERDANT LE PELLET HEATER	
TESTED BY: AUSTRALIAN SOLID FUEL TESTING PTY LTD. 3 GARDEN ST. MORWELL, VIC AUSTRALIA 3840	MODEL NO. SCPH02
SERIAL NO: SCPH02-18-	
TEST REPORT NO: ASFT 17014-1	
DATE TESTED: FEBRUARY 2017	
WHEN TESTED IN ACCORDANCE WITH AS/NZS 4944 & AS/NZS 4596:5978:2007	
MAXIMUM AVERAGE HEAT OUTPUT BURNING WOOD PELLET FUEL	6.9kW
OVERALL AVERAGE EFFICIENCY BURNING WOOD PELLET FUEL	79%
PARTICULATE EMISSIONS FACTOR	0.6g/kg
CATALYTIC COMBUSTION	NO
ELECTRIC SHOCK PROTECTION	CLASS I
INPUT POWER	47 - 180W
RATED VOLTAGE	220 - 240V/50Hz
DESIGNED TO BURN ONLY HIGH QUALITY WOOD PELLETS WITH MOISTURE CONTENT OF LESS THAN 10%.	
MANUFACTURED FOR: SCANDIA HEATING (AUSTRALIA) PTY LTD 58 ACCESS WAY, CARRUM DOWNS, VIC AUSTRALIA 3201 PH: +613 8579 5600	MADE IN CHINA CE
ATTENTION BY LAW THIS APPLIANCE MUST BE RE-INSTALLED BY A LICENSED INSTALLER. PLEASE REFER TO OWNERS MANUAL FOR INSTALLATION SPECIFICATIONS.	

Identification:

The Model Number and Serial Number are located on Compliance Plate on the back the pellet fire. The Item Number is located on product carton.

Affected products have **Model Number SCPH02**, **Item Number 317153** and **Serial Numbers SCPH02-XX-YYYY**, where X and Y may be any number.

Defect: The screws that hold the controller in place, forming part of the earth connection, could become loose. This may allow the earth connection to break which will affect the electrical safety of the pellet heater.

Hazard: Risk of Electric Shock

Action Required:

- Stop using the heater immediately.
- Turn off the power at the wall and disconnect the plug.
- Contact Scandia to assess if an on-site inspection and repair is necessary.

Contact: Please contact Scandia Service on (03) 8579 5911 (8am-4pm AEDT Mon-Fri), or email verdant@scandiagroup.com.au.

See www.productsafety.gov.au for
Australian product recall information