

# Product Safety Recall



## Makita Petrol Line Trimmer

### Models: EM2500L, EM2600L, ER2600L

Sold at NZ retail outlets **between June 2016 and August 2017**

In the interest of user safety, Makita NZ Ltd is undertaking a voluntary safety recall of Makita Petrol Line Trimmer models EM2500L, EM2600L and ER2600L for replacement of Rubber Grommet in fuel tank.

**Defect:** After some period of use, the Grommet may deform.

**Hazard:** When the Grommet deforms, it may cause leakage from fuel tank. No injury has been reported but the leaked fuel poses a fire hazard.

**What to do:** Check the model and serial number of your Line Trimmer (see the illustration). If the model and serial number of your Line Trimmer are within the affected range – stop using it immediately. Take your Trimmer into the store you bought it from or to a nearest Makita Authorised Service Agent. Makita NZ Ltd will arrange free of charge modification.

Affected range of serial numbers:



Model

Serial  
number

EM2500L	from	160500001	to	160500070
EM2600L	from	160400151	to	160400175
	from	160700171	to	160700220
ER2600L	from	160500351	to	160500420
	from	160600001	to	160600175
	from	160700701	to	160700770
	from	160800981	to	160801050
	from	160901001	to	160901070
	from	170200021	to	170200055
	from	170301121	to	170301140
	from	170401296	to	170401330

#### New Zealand Importer/Distributor:

Makita (New Zealand) Ltd  
46 Westpoint Dr, Hobsonville,  
Auckland, New Zealand

#### Contact details:

phone: 0800-MAKITA or 0800-625-482  
email: warranty@makita.co.nz  
website: www.makita.co.nz