

Product Safety Recall



RYOBI 40 Litre Air Compressor

RYOBI 40 Litre 1.8HP Oil Free Direct Drive Upright Air Compressor RA-ACDDU1840
Sold at Bunnings Stores (NZ) from February 2015 to February 2020

Defect: The wiring to the overload switch under the compressor housing is not reinforced insulated (2 layers of insulation) and is in a reachable location.

Hazard: If the user reaches into the inside of the cavity of the compressor body and touches it there is a risk of electric shock.

What to do: Stop using and unplug the RYOBI Compressor from the mains power and return it to your nearest Bunnings store for a replacement new version of the product (when available) or a refund.

Contact details: Techtronic Industries - RYOBI
phone: 0800 028 491
email: recall@ryobi.co.nz
online: www.ryobi.co.nz

See www.recalls.govt.nz for
other New Zealand consumer product recalls